

Nº 8290

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 3-29-71

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM Installed Cleanout


HOUSE NO. 2513

SIZE OF PIPE USED 4"
DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH west Side of House

WAS LATERAL AT CURB? No

WAS ATTACHED TO MAIN No NAME OF CONTRACTOR P. Franks

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



N

LINCOLN WAY

SIGNED S. Sathorn
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS _____

Kelay

Nº 8290

OFFICE OF THE DIRECTOR OF PUBLIC SE
PERMIT TO TAP SEWER

MASSILLON, OHIO.

3-29

RECEIVED OF

Richard Franks

FEE OF \$ *5.*

FOR WHICH PERMISSION IS GRANTED

Ben Shanklin

TO TAP

Repair Sanitary

SEWER ON THE

South Side

OF

Lincoln Way V. D.

AVE.

ST. TYPE OF STREET

Hard

THE PREMISES BEING LOT NO.

8666

HOUSE NO.

2513

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL, AN
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Richard Franks

Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.