N° Following data to be answered by inspector and signed when returned

	DATE INSPECTED 4-2/-7/	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
	HOUSE NO. 500	
	SIZE OF PIPE USED 6	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT 138 Bast of M 70- CURB LINE AND DEPTH 138
	WAS LATERAL AT CURB? 1/25	
	WAS ATTACHED TO MAIN	NAME OF CONTRACTOR Thin lack
	SHOW BY DIAGRAM RELATION OF LATER	RAL TO WALL OF BUILDING SERVED.
	······································	
		And the state of t
		3'1
	A. L.1-	138'
:	SIGNED / Vatham	FILED AT ENGINEER'S OFFICE
	INSPECTOR FOR CITY	· 大大,一种发生和自己的特殊性。

N 9 8295

PERMIT TO TAP SEWER

MASSILLON, OHIO, Chul	19
Shewhach & scarating	EE OF \$5.
FOR WHICH PERMISSION IS GRANTED A. J. Smith, Ju	
TO TAP SEWER ON THE MORTH	
Sandy and. 71.6. AVE. TYPE OF STREET Chip & Sea	<u></u>
THE PREMISES BEING LOT NO. 11374 , HOUSE NO. 50	0
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CIT	Y COUNCIL, AN
OF THE DEPARTMENT OF PUBLIC SERVICE. NAME OF CONTRACTOR NAME OF CONTRACTOR	

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.