8299

REMARKS.

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 8 / / 9 -	If so how and location from WYE 29 MONTH OF US	, د
HOUSE NO. 209 # 11	UP MY 3' DEEP"	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE OF DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	
WAS LATERAL AT CURB? NO	to the company of the	
WAS ATTACHED TO MAIN	S NAME OF CONTRACTOR LI WENGEY	
SHOW BY DIAGRAM RELATION OF L	ATERAL TO WALL OF BUILDING SERVED.	
N —	F3/P6-68	
	50 Berlo	
	< 29'	
SIGNED V. Tathan	FILED AT ENGINEER'S OFFICE	
	그림 아버지는 그는 그는 아이들은 아이들이 가는 아내는 아내는 사람들이 되었다.	

Lufly

PERMIT TO TAP SEWER

MASSILLON, OHIO, April 28	
RECEIVED OF Prefection Cenelapers FEE OF \$ 5	
President Winelakus	
TO TAP Sewer on the South	_
Marcachurette and L.E. AVE. ST. TYPE OF STREET Whip of Seel	
THE PREMISES BEING LOT NO. 4328-N/1-6339 HOUSE NO. 109-211-3/	2 7 1
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL,	1

NAME OF CONTRACTOR WENGEY

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.