Nº 8303 FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED
HOUSE NO. 833
SIZE OF PIPE USED 6 DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT SHEEL LINE AND DEPTH 135 month of MAT 1/2 Deep
WAS LATERAL AT CHEST YOU NAME OF CONTRACTOR Stubach
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.
AS Ben 7/1
SIGNED FILED AT ENGINEER'S OFFICE
- Andrew January (1995年)を Dec March Dec Marc

N_{0} 8303

PERMIT TO TAP SEWER

	MASSILLON, OHIO, May 6
The second se	AASSILLON, OHIO,
RECEIVED OF Shinback	
RECEIVED OF MUNICIPALITY	FEE OF \$
James 7	Varlield
TOR WHICH FERMISSION IS CHARTLES	
TO TAP Sanitary hunce SEWE	RONTHE Wat
of aughter and Dr. VIE AVE. TYPE	OF STREET Chip & list
THE PREMISES BEING LOT NO. 13020	893
THE PREMISES BEING LOT NO.	HOUSE NO.
	·
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE	to. 2323, duly passed by the City Council, an
OF THE DEPARTMENT OF PUBLIC SERVICE.	
NAME OF CONTRACTOR Attinhack	
TARIE OF CONTRACTOR	

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.