

Nº 8350

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 8-13-71

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. _____

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____


SIZE OF PIPE USED _____

WAS LATERAL AT CURB? _____

WAS ATTACHED TO MAIN _____

NAME OF CONTRACTOR Beaver

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



L. Satham
N

SIGNED _____
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE _____

REMARKS HSE RAZED SAN. SEWER Blocked off with
Cement

CUT-OFF

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

Nº 8350

MASSILLON, OHIO, July 29

RECEIVED OF

Beane Excavating Co.

FEE OF \$

5.00

FOR WHICH PERMISSION IS GRANTED

Mrs. Gertrude Jones

TO TAP

CUT-OFF

Sanitary

SEWER ON THE

South

OF

Hatman Ave. W.E.

AVE.

ST. TYPE OF STREET

Chippewa

THE PREMISES BEING LOT NO.

9392

HOUSE NO.

547

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Beane

Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.