Nº 8365

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

WAS LATERAL AT CURB? NO	D-
WAS ATTACHED TO MAIN YES NAME OF CONTRACTOR HOWBET	
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.	•
80 32	
SIGNED W. HAMMEN FILED AT ENGINEER'S OFFICE	

Duply

N° 8365

OFFICE OF THE DIRECTOR OF PUBLIC SER PERMIT TO TAP SEWER

RECEIVED OF MASSILLON, OHIO, Sight. 2 FEE O	
Massillon, Ohio,	1
ME Consold I am	75
RECEIVED OF FEE O	- 5 ⊘ √ √ ·
211 Conald Inc.	•
FOR WHICH BERMISSION IS GRANTED	
TO TAP Sanctary SEWER ON THE South	
TO TAP Sanctary SEWER ON THE SEWER ON THE OF 13470 13470 1419-1	مد
THE PREMISES BEING LOT NO. 13470 HOUSE NO. 1419-1	421
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY CO.	JNCIL, ANE

NAME OF CONTRACTOR Sambett

OF THE DEPARTMENT OF PUBLIC SERVICE.

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.