$\mathbf{N}$ ? 8388 $^{'}$ 

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 11-24-71	FIRST MANHOLE DOWN STREAM WYE 71 N.W. 0 5 MH 8
HOUSE NO. 2421	
SIZE OF PIPE USED 6	DISTANCE FROM FIRST MANHOLE  DOWN STREAM TO DITCH AT  CURB LINE AND DEPTH
WAS LATERAL AT CURB? IVO	
WAS ATTACHED TO MAIN YES	NAME OF CONTRACTOR PLANTS
SHOW BY DIAGRAM RELATION OF LATE	RAL TO WALL OF BUILDING SERVED. 90
	218 15.2 1
	77. 42
N N	(16) FY 45 0 30
SIGNED INSPECTOR FOR CIT	FILED AT ENGINEER'S OFFICE
REMARKS	

## N? 8388

## OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

Massillon.	OHIO, Merender 23
Richard Franks	25.
FOR WHICH PERMISSION IS GRANTED by I Fillie	
TO TAP SEWER ON THE	West
TO TAP SEWER ON THE SEWER ON THE OF STREET.  OF WARTEN CONTROL OF STREET.	Chip of Lie
THE PREMISES BEING LOT NO	
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, D	
OF THE DEPARTMENT OF PUBLIC SERVICE.	
NAME OF CONTRACTOR Transfer	

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.