8389

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

• •		
DATE INSPECTED 1-3-72	IF SO HOW AND LOCATION FROM WYE	136'NortHOSM/ 11
HOUSE NO. 10.38		
SIZE OF PIPE USED C	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	
WAS LATERAL AT CURB? No		
WAS ATTACHED TO MAIN YES	NAME OF CONTRACTOR	R. Franks
SHOW BY DIAGRAM RELATION OF LAT	ERAL TO WALL OF BUILDING SERVED.	
en e	ting the second	₩-1 23 4-
en e		12 M 2 10N 30 B
N		Ty 1 / 20°E
		36% 2 450
*.	6'57	Ach Pro 21
		3 18 11 072
		136'
SIGNED INSPECTOR FOR C	FILED AT ENGINEER'S	OFFICE
	11.5	

Nº 8389

OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

MASSILLON, OHIO, Hamilia 23
RECEIVED OF Richard Franks FEE OF \$ 35.
RECEIVED OFFEE OF \$
FOR WHICH PERMISSION IS GRANTED MAYNAIL FINGE
TO TAR Sanctary West Sewer ON THE South West
of Carline Core ST. Type of STREET Very of Since
THE PREMISES BEING LOT NO. 12337 , HOUSE NO. 1035
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL, ANI
OF THE DEPARTMENT OF PUBLIC SERVICE.
NAME OF CONTRACTOR Michael Franks

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.