

57
✓
N^o 8394

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 12-9-71

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 816

SIZE OF PIPE USED 4"



DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____

WAS LATERAL AT CURB? _____

WAS ATTACHED TO MAIN _____

NAME OF CONTRACTOR Beaver

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED _____

J. Latham

INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE _____

REMARKS _____

Cit. off

Nº 8394

OFFICE OF THE DIRECTOR OF PUBLIC SEWERS
PERMIT TO TAP SEWER

MASSILLON, OHIO.

November 23

RECEIVED OF

Beane Excavating Co.

FEE OF \$

5.

FOR WHICH PERMISSION IS GRANTED

Billie Peterson

Cit. off
TO TAP

Sanitary

SEWER ON THE

North

OF

Tremont Ave. S.E.

AVE.
ST. TYPE OF STREET

Chip & Seal

THE PREMISES BEING LOT NO.

9501

HOUSE NO.

816

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Beane

Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.