## **vº** 8406

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

HOUSE NO. 1018  SIZE OF PIPE USED (1)  WAS LATERAL AT CERRE?	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT OURS LINE AND DEPTH 197 NOVTH OF MANHOLE PLOTO TO THE TOTAL OF MANHOLE DOWN STREAM TO DITCH AT OURS LINE AND DEPTH 197 NOVTH OF MANHOLE PLOTO
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR MY GOVETONSINGEL
SHOW BY DIAGRAM RELATION OF LATE	D cto
N —	
SIGNED W. HAMMER INSPECTOR FOR CIT	FILED AT ENGINEER'S OFFICE

## Nº 8406

## PERMIT TO TAP SEWER

MASSILLON, OHIO, 11-29	
Massillon, Ohio, 77 U	
Lesten No and	FEE OF \$ 25.
Roland Fauxt	
FOR WHICH PERMISSION IS GRANTED	
TO TAR Sanitary SEWER ON THE East	•
of Sanitary Sewer on the East  AVE. AVE. TYPE OF STREET Chip & Six	<u>C</u>
THE PREMISES BEING LOT NO. 1216 4 HOUSE NO. 1018	
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CIT	TY COUNCIL, AN
OF THE DEPARTMENT OF PUBLIC SERVICE.	

Guetinelager

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.