

N^o 8413 ✓

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 12-8-71IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____HOUSE NO. 1807SIZE OF PIPE USED 6"DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH94' EAST OF MH 9' deepWAS LATERAL AT CURB? YES


PROP

WAS ATTACHED TO MAIN NO

NAME OF CONTRACTOR

H & W

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

S. Latham

INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS _____

Nº 8413

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, Nov. 30 191
RECEIVED OF Richard Crescenze FEE OF \$ 2.00
FOR WHICH PERMISSION IS GRANTED Richard Crescenze
TO TAP Sanitary SEWER ON THE South
OF Carlene AVE. TYPE OF STREET Chip & Seal
THE PREMISES BEING LOT NO. 12247 HOUSE NO. 1807

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

H & W Contractor Inc.

Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.