

N^o 8423

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

DATE INSPECTED 12-2-71

IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM 152' South of MH 13' DEEP

HOUSE NO. 395

DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH

SIZE OF PIPE USED 6"


WAS LATERAL AT CURB? —

WAS ATTACHED TO MAIN YES

NAME OF CONTRACTOR

WENGER

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

William Hammer

Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

Nº 8423

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, DEC. 2

RECEIVED OF ELIZABETH RAMSEY FEE OF \$ 2.

FOR WHICH PERMISSION IS GRANTED WENGER

TO TAP SAN SEWER ON THE WEST

OF FORD ST. N.W. AVE. ST. TYPE OF STREET CHURCH ST.

THE PREMISES BEING LOT NO. 13441, HOUSE NO. 395

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND BY THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR WENGER

Note: This permit covers work outside of building only. Any work inside of building is subject to Massillon Board of Health Regulations.