$N^{\underline{o}}$ -8431 following data to be answered by inspector and signed when returned

DATE INSPECTED 12-16-71	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
SIZE OF PIPE USED Prop WAS LATERAL AT-CURB?	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT 210 least of 14/ 9 0
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR MIN MELD CY BAUM
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL	L OF BUILDING SERVED.
	12'
	30° G Preep 48°
SIGNED Inspector for City	FLED AT ENGINEER'S OFFICE
And the world of the second of	grander and the contract of th

№ 8431

OFFICE OF THE DIRECTOR OF PUBLIC SER PERMIT TO TAP SEWER

MASSILLON, OHIO. A Gri - Z
MASSILLON, OHIO, A GO 2 MASSILLON, OHIO, A GO 2 RECEIVED OF FEE OF \$ 23
RECEIVED OF FEE OF \$ 2.5
FOR WHICH PERMISSION IS GRANTED TO AND SERVICE AND
TO TAP SEWER ON THE BOTTA
of Carlene St. Type of Street Slige & Cal
THE PREMISES BEING LOT NO. 12251, HOUSE NO. 1738
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND F
OF THE DEPARTMENT OF PUBLIC SERVICE.
NAME OF CONTRACTOR

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.