

✓ FOLLOWING DATA TO BE ANSWERED BY INSPECTOR  
 N<sup>o</sup> 8444 AND SIGNED WHEN RETURNED

DATE INSPECTED 12-23-71

IF SO HOW AND LOCATION FROM  
 FIRST MANHOLE DOWN STREAM

HOUSE NO. 1839

DISTANCE FROM FIRST MANHOLE  
 DOWN STREAM TO DITCH AT  
 CURB LINE AND DEPTH

SIZE OF PIPE USED 6"

Prop

WAS LATERAL AT CURB? Prop Yes


180 ft north of MH 8'

M. Holderbaum  
~~H. H. H.~~

WAS ATTACHED TO MAIN No

NAME OF CONTRACTOR

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED L. Satter  
 Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

Nº 8444

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE  
PERMIT TO TAP SEWER

MASSILLON, OHIO, Dec 7

RECEIVED OF Robert R. Fitting FEE OF \$ 2.50

FOR WHICH PERMISSION IS GRANTED Robert R. Fitting

TO TAP Sanitary SEWER ON THE West

OF Meacham Brook <sup>AVE</sup> ST. TYPE OF STREET Ship & Seal

THE PREMISES BEING LOT NO. 12958, HOUSE NO. 1839

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND  
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Holderbaum

**Note:** This permit covers work outside of building only. Any work  
walls of building is subject to Massillon Board of Health Regulations.