FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 12-31-7/ HOUSE NO. 2/17	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH 119 west of 14
WAS LATERAL AT SURBY YES	M. Holderbann
WAS ATTACHED TO MAINSHOW BY DIAGRAM RELATION OF LATERAL TO WALL	NAME OF CONTRACTOR
· · · · · · · · · · · · · · · · · · ·	7 /01 231 4
	वह
	22°B0.
	110'
SIGNED Inspector for City	FILED AT ENGINEER'S OFFICE

Nº 8458

OFFICE OF THE DIRECTOR OF PUBLIC SEF PERMIT TO TAP SEWER

	MASSILLON, OHIO, Louiselin 27,
RECEIVED OF Halduchaun	FEE OF \$ _25
FOR WHICH PERMISSION IS GRANTED Market J.	Linian
TO TAP Sanutary SEV	VER ON THE South
OF Carline Are. S. W. AVE. TY	PE OF STREET Chip & Lise
THE PREMISES BEING LOT NO. 1118	, HOUSE NO. 2/1/7
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO	
NAME OF CONTRACTOR Haldubaum	,

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.