## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED $1-6-72$	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO. 20 SIZE OF PIPE USED 6	DISTANCE FROM FIRST MANHOLE  DOWN STREAM TO DITCH AT  CURB LINE AND DEPTH
WAS LATERAL AT CURB?	and the second of the second o
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL	L OF BUILDING SERVED.
	N. CURB.
SIGNED Sattlann Inspector for City	FILED AT ENGINEER'S OFFICE
REMARKS	

(nt-9)

**№** 8462

## OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

AMA SAM	SILLON, OHIO, Surenetin 30,	
RECEIVED OF Estick Wuching Co	5 FEE OF \$	
FOR WHICH PERMISSION IS GRANTED Carl Cour		
SPT - 0 F F La siction SEWER (	ON THE WATER	
OF Charles aw J. W. ST. TYPE OF	STREET And Sugar	
THE PREMISES BEING LOT NO. 212	/	
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19	-1971 DULY PASSED BY THE CITY COUNCIL, AND I	

NAME OF CONTRACTOR Shield Whiching Co.

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.