

✓
No 8465

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 12-31-71

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO. 2443

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

SIZE OF PIPE USED 4"

WAS LATERAL AT CURB?


Prop Repair

WAS ATTACHED TO MAIN

NAME OF CONTRACTOR

R FRANKS

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

J. L. Latham
Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

repaired 4" pipe around leaks

Repair
N^o 8465

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO,

December 31

RECEIVED OF

Franks

FEE OF \$

25

FOR WHICH PERMISSION IS GRANTED

Thomas Reese

TO TAP

Sanitary

SEWER ON THE

South

OF

4-14-E

AVE.
ST.

TYPE OF STREET

Hard surface

THE PREMISES BEING LOT NO.

4914

HOUSE NO.

2443

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Franks

**Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.**