FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 3-6-22	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT GURB LINE AND DEPTH. 194 //5, a f M 9 / 2 Prop
WAS ATTACHED TO MAIN A SHOW BY DIAGRAM RELATION OF LATERAL TO WALL	NAME OF CONTRACTOR 92
SHOW BY DIAGRAM RELATION OF LATERAL TO WAL	. 18
	7000
	53' 1
N	90 → q
•	
1011.	- 194
SIGNED attack	FILED AT ENGINEER'S OFFICE
Inspector for City	
REMARKS	

Nº 8481

OFFICE OF THE DIRECTOR OF PUBLIC SER PERMIT TO TAP SEWER

N	iassillon, ohio, Feb. 22
	cace FEE OF \$ 35
FOR WHICH PERMISSION IS GRANTED All L.	*
TO TAP Sanitary SEWE	
OF Margilea La. S.W. AVE. TYPE	· · · · · · · · · · · · · · · · · · ·
THE PREMISES BEING LOT NO. 12998	
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO.	· · · · · · · · · · · · · · · · · · ·
OF THE DEPARTMENT OF PUBLIC SERVICE.	
NAME OF CONTRACTOR A LA LACTOR	

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.