

No 8490

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

DATE INSPECTED

5-3-72

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO.

715

SIZE OF PIPE USED

6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

151' NORTH OF M 8'D

WAS LATERAL AT CURB?

Propo

YES



WAS ATTACHED TO MAIN

NO

NAME OF CONTRACTOR

G. MALAVITO

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

[Signature]
Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

Nº 8490

OFFICE OF THE DIRECTOR OF PUBLIC SEW
PERMIT TO TAP SEWER

MASSILLON, OHIO, May 2

RECEIVED OF

Malanite Electric

FEE OF \$

FOR WHICH PERMISSION IS GRANTED

Remedy

TO TAP

Sanitary

SEWER ON THE

West

OF

Langdon Ave. NE

AVE.

ST. TYPE OF STREET

Chip & Seal

THE PREMISES BEING LOT NO.

13076

HOUSE NO.

715

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND I
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Malanite

**Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.**