**№** 8492

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM			
HOUSE NO	DISTANCE FROM FIRST MANHOLE			
	DOWN STREAM TO DITCH AT CURB LINE AND DEPTH			
WAS LATERAL AT CURB?				
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR			
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.				
	en de la companya de La companya de la co			
	·			
SIGNED	FILED AT ENGINEER'S OFFICE			
Inspector for City	FILED AT ENGINEER'S OFFICE			
	• •			
REMARKS	***************************************			

CUT-OFF

**№** 8492

## OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

	MASSILLON,	оню,	May	3	1
RECEIVED OF Beanu Erca	ualing		J	FEE OF \$	5.
FOR WHICH PERMISSION IS GRANTED 11 selecasi			- 14 Acr - 17 10 arr - 10 - 10 - 10 - 10 - 10 - 10 - 10 -	** ** ** ** ** ** ** ** ** ** ** ** **	
CUT-OFF LATULARY SEV			Liet		
OF 11 11 11 11 AVE. TY.					
THE PREMISES BEING LOT NO. $1999$			and the same		
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO	). 19-1971 D	DULY PASSE	D BY THE CIT	Y COUNCIL,	AND F

NAME OF CONTRACTOR Beance

OF THE DEPARTMENT OF PUBLIC SERVICE.

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.