

N^o 8505

✓ FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 6-7-72

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO. 2113

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

SIZE OF PIPE USED 6"


162' NORTH of MH 9

WAS LATERAL AT CURB? YES

WAS ATTACHED TO MAIN NO

NAME OF CONTRACTOR CREST EXCA.

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED WM HAMMER

Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

Nº 8505

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, *June 6*

RECEIVED OF *Crest Excavating, Inc.*

FEE OF \$ *2.00*

FOR WHICH PERMISSION IS GRANTED *Richard Reese*

TO TAP *Sanitary*

SEWER ON THE *East*

OF *Margilee Dr. S.W.*

AVE.
ST.

TYPE OF STREET *Chapel*

THE PREMISES BEING LOT NO. *12980*

HOUSE NO. *4113*

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND IN
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR *Crest*

**Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.**