## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR

| UO. | / |
|-----|---|
|-----|---|

## Nº 8514 AND SIGNED WHEN RETURNED

| DATE INSPECTED   | IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM |
|--|---|
| HOUSE NO.  | DISTANCE FROM FIRST MANHOLE  TOOWN STREAM TO DITCH AT |
| WAS LATERAL AT CURB?   |   |
| WAS ATTACHED TO MAINSHOW BY DIAGRAM RELATION OF LATERAL TO   | NAME OF CONTRACTOR                                    |
|  |   |
| en e   |   |
| e por transfer de la companya de la |   |
| •••  |   |
| ,  | FILED AT ENGINEER'S OFFICE                            |

VOID- ALREADY HAD PERMIT #8497

Nº 8514

## OFFICE OF THE DIRECTOR OF PUBLIC SER PERMIT TO TAP SEWER

| MASSILLON, OHIO, JULIE JO.,   |  |  |
|---|--|--|
| RECEIVED OF Malawite Excavating FEE OF \$ 25  |  |  |
| FOR WHICH PERMISSION IS GRANTED Jask Harry, June:   |  |  |
| TO TAP Sanctary SEWER ON THE Marth  |  |  |
| OF Javi dw 716 AVE. TYPE OF STREET Chip & Luce  |  |  |
| THE PREMISES BEING LOT NO. 12559, HOUSE NO. 672 622   |  |  |
| WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND I<br>OF THE DEPARTMENT OF PUBLIC SERVICE. |  |  |
| NAME OF CONTRACTOR 21/14/14/14/14   |  |  |

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.