

N^o 8518

✓ FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED

7-12-72

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO.

2304

SIZE OF PIPE USED

6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

26' EAST of WH 5 1/2'

WAS LATERAL AT CURB?

Prop YES


WAS ATTACHED TO MAIN

NO

NAME OF CONTRACTOR

R. FRANKS

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

N
4

SIGNED

S. L. Latham

Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

Nº 8518

OFFICE OF THE DIRECTOR OF PUBLIC SER
PERMIT TO TAP SEWER

MASSILLON, OHIO,

RECEIVED OF

Milton Linsack

FEE OF \$

3.50

FOR WHICH PERMISSION IS GRANTED

Frank George Linsack

TO TAP

Sanitary

SEWER ON THE

North

OF

Stearns Rd N.E.

AVE.

ST. TYPE OF STREET

Chippewa

THE PREMISES BEING LOT NO.

13018

, HOUSE NO.

2304

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND F
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Franks

**Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.**