## **N**º 8519 ∨

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 7-14-72	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO. 2/04	DISTANCE FROM FIRST MANHOLE  DOWN STREAM TO DITCH AT  GHRE LINE AND DEPTH 52 1, 0 f M 9 0,0
WAS LATERAL AT-GURB?	Prop E CLICK
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR Q. DISMB
SHOW BY DIAGRAM RELATION OF LATERAL TO WAL	L OF BUILDING SERVED.
	128
<del></del>	N 7'0
	1 /52
	16/2 9'P
SIGNED Settlement	FILED AT ENGINEERIN OFFICE
Inspector for City	FILED AT ENGINEER'S OFFICE
REMARKS	
NUMBER OF THE PROPERTY OF THE	

Nº 8519

## OFFICE OF THE DIRECTOR OF PUBLIC SER PERMIT TO TAP SEWER

MASSILLON, OHIO, JULIA
RECEIVED OF EARL GLICK FEE OF \$ 2.
FOR WHICH PERMISSION IS GRANTED EARL GILICK
TO TAP SALVIT ARY SEWER ON THE UEST
OF MARGILEE AVE. TYPE OF STREET CHIPY SEAL
THE PREMISES BEING LOT NO. $12982$ , HOUSE NO. $2104$
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND I OF THE DEPARTMENT OF PUBLIC SERVICE.

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.