Nº 8524

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 2-31-72	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	·
HOUSE NO. 12/5	DISTANCE FROM FIRST MANHOLE	
SIZE OF PIPE USED	DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	
WAS LATERAL AT GURB?		
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR REDUCE	CEMENTEO
SHOW BY DIAGRAM RELATION OF LATERAL TO WAL	· •	CEMENTED COT OFF GOD
1	20'	·
1		
	- Commence	162'-
SIGNED Lathana	FILED AT ENGINEER'S OFFICE	
Inspector for City		
DEMARKS		

'ut - 44

Nº 8524

OFFICE OF THE DIRECTOR OF PUBLIC SE PERMIT TO TAP SEWER

		MASSIL	LON, OHI	o, July	31	
RECEIVED OF BAN	<u>nu 6 je</u>	Lavating	Co	0 0	FEE OF \$	3
FOR WHICH PERMISSION IS GRAN	TED <u> </u>	athy S. K	telico	ild tei	· · · · · · · · · · · · · · · · · · ·	
CUT OF Samutany		SEWER ON	/ THE	Vacid		
of It almost J.					cerence.	
THE PREMISES BEING LOT NO					pr.	•
WORK TO BE DONE IN ACCORDANC	CE WITH ORDIN	NANCE NO. 19-19	71 DULY	PASSED BY THE	CITY COUNCIL, A	AND.
OF THE DEPARTMENT OF PUBLIC	27					
NAME OF CONTRACTOR	Lacrece	_				

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.