Following data to be answered by inspector No. 8531 and signed when returned

DATE INSPECTED 8-21-27 IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO. 1019 DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH 10 South of My 6
WAS LATERAL AT CURB? YES WAS ATTACHED TO MAIN REAL OF CONTRACTOR OF MALANTY
WAS ATTACHED TO MAIN NAME OF CONTRACTOR STALAULIE!
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.
0
AS Ben D
521 KGBERP
I Sattleman
SIGNED FILED AT ENGINEER'S OFFICE Inspector for City
그는 사람들은 그는 그 점점을 가고 있다면 가장 가장 사람들이 되었다. 그는 사람들이 되었다면 살아보는 것이 되었다.

№ 8531

OFFICE OF THE DIRECTOR OF PUBLIC SER PERMIT TO TAP SEWER

17-15

	MASSILLON, OHIO,_	Chargeat 18	
RECEIVED OF A Chart Stick	<u> </u>	FEE OF \$ 22.5	
FOR WHICH PERMISSION IS GRANTED MATheway Hallale			
TO TAP SANCTARY SEV	VER ON THE	<u> Vist</u>	
OF 21/4 A 1 1 AVE. TY	PE OF STREET	<u>nggluc</u>	
THE PREMISES BEING LOT NO. 1113	, House	E NO. 1619	
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO OF THE DEPARTMENT OF PUBLIC SERVICE.			
NAME OF CONTRACTOR MARIETTE			

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.