## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 8-2/17 IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO. 7/4  DISTANCE FROM FIRST MANHOLE  DOWN STREAM TO DITCH AT  CURB LINE AND DEPTH 141 MOUL OF 19 DE
WAS LATERAL AT CHAR?
WAS ATTACHED TO MAIN NAME OF CONTRACTOR CARALA VILLE SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.
N - V
30 B my 1
SIGNED FILED AT ENGINEER'S OFFICE 141
REMARKS

**№** 8537

## OFFICE OF THE DIRECTOR OF PUBLIC SER PERMIT TO TAP SEWER

	MASSILLON, OHIO, Andrews III.
RECEIVED OF MALENITE	FEE OF \$ _2_5
FOR WHICH PERMISSION IS GRANTED 74	711 ° 71 255
то тар	SEWER ON THE East
of Jandinand L. 1. 1/6 AVE. ST.	and the same of th
THE PREMISES BEING LOT NO. 13004	, HOUSE NO
	NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND I
NAME OF CONTRACTOR Manute	••

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.