

11-26

✓ FOLLOWING DATA TO BE ANSWERED BY INSPECTOR  
AND SIGNED WHEN RETURNED

N<sup>o</sup> 8540

DATE INSPECTED 9-6-77

IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM 99' NORTH 05° MH 6'D

HOUSE NO. 102

DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH

SIZE OF PIPE USED 6"


WAS LATERAL AT CURB? No

WAS ATTACHED TO MAIN Yes

NAME OF CONTRACTOR

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

R. MARKS



RAVISON SE

SUNSET 5

132' 6" V.P.J.R.

SIGNED

*N. Latham*  
Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

11-10

Nº 8540

OFFICE OF THE DIRECTOR OF PUBLIC SER  
PERMIT TO TAP SEWER

MASSILLON, OHIO,

September 5

RECEIVED OF

Russ Marks

FEE OF \$

35

FOR WHICH PERMISSION IS GRANTED

David Marks

TO TAP

Sanitary

SEWER ON THE

North

OF

Parkman Ch. S. E.

AVE.  
ST.

TYPE OF STREET

Chapin St

THE PREMISES BEING LOT NO.

4784

HOUSE NO.

102

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND I  
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Marks

**Note:** This permit covers work outside of building only. Any work  
walls of building is subject to Massillon Board of Health Regulations.