FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

_	·
DATE INSPECTED $9-19-72$	IF SO HOW AND LOCATION FROM . FIRST MANHOLE DOWN STREAM
HOUSE NO. 425	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB?	
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR M. WEZUEY
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL	L OF BUILDING SERVED.
	7'0p 42 42 18'
SIGNED / Hann	FILED AT ENGINEER'S OFFICE
The second secon	

Nº 8542

OFFICE OF THE DIRECTOR OF PUBLIC SER PERMIT TO TAP SEWER

	MASSILLON,	OHIO,	Sil	_} (18	1
RECEIVED OF Made Wear	ull		/		FEE OF \$	22
FOR WHICH PERMISSION IS GRANTED Tayne	Rea	مستا محليك				•
TO TAP Sancing SEV	WER ON THE		7/20	7		
OF Face St. M.W. AVE. TY	PE OF STREET	T(Chep	<u> </u>	g Legender	-
THE PREMISES BEING LOT NO. P. 1. 1217111 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1			-	-		
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO OF THE DEPARTMENT OF PUBLIC SERVICE.						AND I
NAME OF CONTRACTOR DECEMBER						

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.