## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR Nº 8551 AND SIGNED WHEN RETURNED

DATE INSPECTED / 676-72	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM LLYP 258 COST of 141
HOUSE NO. OUEY SIZE OF PIPE USED 6 1/	DISTANCE FROM FIRST MANHOLE  DOWN STREAM TO DITCH AT  CURB LINE AND DEPTH
WAS LATERAL AT CURB? NO	
WAS ATTACHED TO MAIN YES	NAME OF CONTRACTOR D. ROCETS
SHOW BY DIAGRAM RELATION OF LATERAL TO WAL	L OF BUILDING SERVED.
	64'
and the second of the second o	23'
1 July	4.100 4.100
SIGNED Inspector for City	FILED AT ENGINEER'S OFFICE
REMARKS	The second of th

I Howald

Nº 8551

## OFFICE OF THE DIRECTOR OF PUBLIC SER PERMIT TO TAP SEWER

	برسم سنتمير كممو
	MASSILLON, OHIO, 400 7
Tracis & Sous	FEE OF \$ 23
RECEIVED OF	PEE OF \$ -
RECEIVED OF REGION OF SANS	Scott SMHA
/ h	
TO TAP Lanctury SEWE	OF STREET Land Layer
+ Ti Willam an . 71.6	
OF AVE. ST. TYPE	OF STREET HAN LUGACE
P 2	T-1/
THE PREMISES BEING LOT NO. 4.7.714.71	, HOUSE NO
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO.	19-1971 DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.	
4-7	
NAME OF CONTRACTOR 11 C-4.60	\\\\
* · · · /	

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.