FOLLOWING DATA TO BE ANSWERED BY INSPECTOR N° 8557 AND SIGNED WHEN RETURNED

DATE INSPECTED 10-9-72	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM WYE 48' SOUT IL OF MY
HOUSE NO. OVEY	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB?	
W \S ATTACHED TO MAIN	1 · · · · · · · · · · · · · · · · · · ·
SHOW BY DIAGRAM RELATION OF LATERAL TO WA	ALL OF BUILDING SERVED.
and the state of t	
In C	- H 3 Km
N —	
•	
The state of the s	$\sim 10^{-1}$ $\sim 10^{-1}$
	48'
, ,	
	1 30 BeND
SIGNED Inspector for City	FILED AT ENGINEER'S OFFICE

4 Unul

№ 8557

OFFICE OF THE DIRECTOR OF PUBLIC SEF PERMIT TO TAP SEWER

MASSILLON, OHIO, 10/9/
RECEIVED OF RECEIV
FOR WHICH PERMISSION IS GRANTED Collan - Scatt SMHA
TO TAP Sanctary SEWER ON THE Sants
of It Man and 11.6 AVE. TYPE OF STREET Chip of Sice
THE PREMISES BEING LOT NO. $0.9.71971$, HOUSE NO. $161-163-165-16$
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND OF THE DEPARTMENT OF PUBLIC SERVICE.

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.