

✓
N^o 8561

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 2-19-23

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

447 42.5 West

HOUSE NO. 424-26-28-30

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

SIZE OF PIPE USED 6"

WAS LATERAL AT CURB? NO


WAS ATTACHED TO MAIN YES

NAME OF CONTRACTOR

D. Rogers

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

N
4



42.5

SIGNED S. Latham
Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

4 Units

Nº 8561

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, 10/9

RECEIVED OF

Rogers & Sons

FEE OF \$

25

FOR WHICH PERMISSION IS GRANTED

Edman - Scott S M H A

TO TAP

Sanitary

SEWER ON THE

East

OF

Windsor Ave. S.E.

AVE.

ST. TYPE OF STREET

Chippewa

THE PREMISES BEING LOT NO.

17 N. 7. 326

HOUSE NO.

424-426-428-4

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Rogers

**Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.**