Nº 8572 FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DISTANCE FRO. DOWN STREAM	D LOCATION FROM WY & INSTALLE & S7 W OF MY & DEEP M FIRST MANHOLE 1 TO DITCH AT 10 DEPTH
WAS LATERAL AT CURB? NO	unit production with a second
WAS ATTACHED TO MAIN YES NAME OF CON	TRACTOR D. ROSSELS
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING	$1 \qquad (I \qquad I)$
	1/3
2 Marie de la companya del companya de la companya del companya de la companya del companya de la companya de la companya de la companya del companya de la	5 porp
SIGNED Inspector for City	FILED AT ENGINEER'S OFFICE
	The state of the s

№ 8572

OFFICE OF THE DIRECTOR OF PUBLIC SER PERMIT TO TAP SEWER

MASSILLON, OHIO, 10/9
RECEIVED OF Augus & Seas FEE OF \$ 25
O. h. Sott & MA
FOR WHICH PERMISSION IS GRANTED COLLECTION OF THE PERMISSION OF THE PERMIS
TO TAP Landary SEWER ON THE Thet
of Mudulil It 16 AVE. TYPE OF STREET Chapt since
THE PREMISES BEING LOT NO. $0.0000000000000000000000000000000000$
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND I
OF THE DEPARTMENT OF PUBLIC SERVICE.
NAME OF CONTRACTOR / / AGEN
Note: This permit covers work outside of building only. Any work

walls of building is subject to Massillon Board of Health Regulations.