FOLLOWING DATA TO BE ANSWERED BY INSPECTOR 8580 AND SIGNED WHEN RETURNED

DATE INSPECTED 12-13-22	IF SO HOW AND LOCATION IN THE ST MANHOLE DOWN	ON FROM	ST	BIN	rjf	7 ' D
HOUSE NO. 1224-26-28-30	DISTANCE PROW FIRST	MANHOLE				
SIZE OF PIPE USED.	DOWN STREAM TO DITCH CURB LINE AND DEPTH					
WAS LATERAL AT CURB? NO.		• .				
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR	·	۵.	POGT	115	
SHOW BY DIAGRAM RELATION OF LATERAL TO WAL	L OF BUILDING SERVED.				To the state of th	
		Res .				10,
r.		-				1 3 mg 6
N =					201	J
	•				0'	

4 Unit

№ 8580

OFFICE OF THE DIRECTOR OF PUBLIC SEF PERMIT TO TAP SEWER

MAS	SILLON, OHIO, 16/19						
RECEIVED OF Pages & Sans	FEE OF \$ 25						
RECEIVED OF PAGES & SCOTT SHAA FEE OF \$ \$35							
TO TAP SEWER (ON THE Gat						
OF 16 TYPE OF	STREET Chip of Jeel						
THE PREMISES BEING LOT NO. 25 395	A-2. , House No./334-1936-1938-,						
VORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19	-1971 DULY PASSED BY THE CITY COUNCIL, AND I						

32

AME OF CONTRACTOR JACK

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.