

N^o 8589

✓ FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 10-20-72

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM ^{UP} "wy" 6' west of RD ?

HOUSE NO. 114

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH


WAS LATERAL AT CURB? No

WAS ATTACHED TO MAIN YES

NAME OF CONTRACTOR

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

R. FRANKS



SIGNED J. Nathan
Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

Nº 8589

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO,

October 18

RECEIVED OF

Richard Frank

FEE OF \$

25

FOR WHICH PERMISSION IS GRANTED

William G. Gagnier

TO TAP

Sanitary

SEWER ON THE

North

OF

Arch. Ave. S.E.

AVE.
ST.

TYPE OF STREET

Chas. & Lusk

THE PREMISES BEING LOT NO.

2066-2067

HOUSE NO.

111

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND IN
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Frank

**Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.**