√º 8595

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 16-13-72 HOUSE NO. 744	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
SIZE OF PIPE USED.	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT 2/8 NOVTH of My 9
WAS LATERAL AT OURD?	M.P
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR THE MALAUITIE
SHOW BY DIAGRAM RELATION OF LATERAL TO WAL	L OF BUILDING SERVED.
N.	45 BEN 48 145 "
SIGNED Vathorm	ELLED AT ENGINEEDIG OFFICE
Inspector for City	FILED AT ENGINEER'S OFFICE
1	

№ 8595

OFFICE OF THE DIRECTOR OF PUBLIC SER PERMIT TO TAP SEWER

	MASSILLON, OHIO, Mercimber 9,	
RECEIVED OF Malaryth Etc	sentating FEE OF \$ 40	
FOR WHICH PERMISSION IS GRANTED ACCOUNTED Married Marr		
TO TAPSE	WER ON THE	
OF MANUEL AVE. TY.	PE OF STREET CAR FLOOR	
THE PREMISES BEING LOT NO. 11134	, HOUSE NO	
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND OF THE DEPARTMENT OF PUBLIC SERVICE.		
NAME OF CONTRACTOR 2/12/2017	<u></u>	

Note: This permit covers work outside of building only. Any work

walls of building is subject to Massillon Board of Health Regulations.