Nº 8599

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

	コープ	ENSTALL =d	
DATE INSPECTED 11 - 30 - 7 Z	IF SO HOW AND LOCATION FROM	MYC 109 A South a	1
	FIRST MANHOLE DOWN STREAM	MYE - 124 January	
HOUSE NO. 2/3	<ur_< td=""><td>•</td><td></td></ur_<>	•	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT		
SIZE OF PIPE USED	CURB LINE AND DEPTH		
WAS LATERAL AT CURB?			
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR	R. Franks	
•			i
SHOW BY DIAGRAM RELATION OF LATERAL TO WAL	E OF BUILDING SERVED,	1	
			[
		4	
		1	
Juda-manana.	_ n /		
·		<u>4</u>	ı
·	•nvice • · · · · · · · · · · · · · · · · · ·		
		1=30°B-6ND	
Ω		12/- 1001	
	•	92	
SIGNED / J. J. J. L.	777	NGINEER'S OFFICE	
Inspector for City	- Marita	1	

№ 8599

OFFICE OF THE DIRECTOR OF PUBLIC SER PERMIT TO TAP SEWER

in a second seco	MASSILLON, OHIO, Therentha 15
RECEIVED OF AJENTA	Lone FEE OF \$ 25
FOR WHICH PERMISSION IS GRANTED 1944	m Hanseld
TO TAP CALLE SEAL SE	
of	
THE PREMISES BEING LOT NO. 6 355	, HOUSE NO
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NOT THE DEPARTMENT OF PUBLIC SERVICE.	
NAME OF CONTRACTOR 2	

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.

*##.