

Nº

8605

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 12-18-72

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO.

1710

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

SIZE OF PIPE USED

6"

WAS LATERAL AT CURB?

yes

WAS ATTACHED TO MAIN


no

NAME OF CONTRACTOR

M. HOLDERBAUM

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

N



SIGNED

V. Nathan

Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

Drilled Hole Through Sewer for Guide wire from

Repair
Nº 8605

17-12 or 15
OFFICE OF THE DIRECTOR OF PUBLIC SEW
PERMIT TO TAP SEWER

MASSILLON, OHIO, *December 18*

RECEIVED OF *Haldenbaum*

FEE OF \$ *25*

FOR WHICH PERMISSION IS GRANTED *J. Harris*

TO TAP *Sanitary*

SEWER ON THE *East*

OF *13th St. S.E.*

AVE.

ST. TYPE OF STREET *chip & seal*

THE PREMISES BEING LOT NO. *D-1-298*

HOUSE NO. *1710*

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR *Haldenbaum*

Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.