

N^o 8609

✓ FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED

1-23-73

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO.

419

SIZE OF PIPE USED

6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

40' EAST OF MH 9' DEEP

WAS LATERAL AT CURB?


YES

WAS ATTACHED TO MAIN

NAME OF CONTRACTOR

FRANKS

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

William Hammer

Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

Nº 8609

OFFICE OF THE DIRECTOR OF PUBLIC SEWERS
PERMIT TO TAP SEWER

MASSILLON, OHIO,

Jan. 22

RECEIVED OF

Richard Franks

FEE OF \$ 2.15

FOR WHICH PERMISSION IS GRANTED

Paul R. Michael

TO TAP

Sanitary

SEWER ON THE

South

OF

San Antonio St.

AVE.

ST. TYPE OF STREET

Chip & Seal

THE PREMISES BEING LOT NO.

12568

HOUSE NO.

419

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Franks

Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.