8611

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 2-5-7-3 IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO. DISTANCE FROM FIRST MANHOLE SIZE OF PIPE USED CURB LINE AND DEPTH 197 West of MI
WAS LATERAL AT GURB?
WAS ATTACHED TO MAIN A D NAME OF CONTRACTOR ESCICA WYECKING
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.
WALLACE S.E. SAN
SIGNED FILED AT ENGINEER'S OFFICE
Inspector for City
REMARKS

Cit-off

№ 8611

OFFICE OF THE DIRECTOR OF PUBLIC SEF PERMIT TO TAP SEWER

	MASSILLON, OHIO	o, Joen :	14.	
RECEIVED OF Call One	<u> </u>		FEE OF \$ 5	
FOR WHICH PERMISSION IS GRANTED	Oxu	<i>,</i>		
TOTAP Sanitary SE	EWER ON THE	Harth	**	
of Wallace and S.E. AVE. T.	YPE OF STREET	Chy & Lea	L	
THE PREMISES BEING LOT NO. 1465	, но	JSE NO. 54	.0	
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND OF THE DEPARTMENT OF PUBLIC SERVICE.				
NAME OF CONTRACTOR & Slick) Vinc	Ling			
	4	w.		

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.