


6-3

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
N^o 8617 AND SIGNED WHEN RETURNED

DATE INSPECTED 2-3-73 IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM INSTALL CLEANOUT
HOUSE NO. 203
SIZE OF PIPE USED 6" DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH AT HOUSE
WAS LATERAL AT CURB? NO
WAS ATTACHED TO MAIN NO NAME OF CONTRACTOR HOLZER BAUM
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

N
↑



6' 2' 0"

SIGNED

J. S. Latham
Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

Repair
Nº 8617

OFFICE OF THE DIRECTOR OF PUBLIC SEW
PERMIT TO TAP SEWER

MASSILLON, OHIO, *February 2*

RECEIVED OF *Holdenhausen*

FEE OF \$ *25*

FOR WHICH PERMISSION IS GRANTED *Clarence Backus*

TO TAP *Sanitary*

SEWER ON THE *West*

OF *6th St. N.W.*

AVE.
ST. TYPE OF STREET

Chip & Seal

THE PREMISES BEING LOT NO. *9290*

HOUSE NO. *203*

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR *Holdenhausen*

Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.