## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR 8627 AND SIGNED WHEN RETURNED

DATE INSPECTED 3-15-7/3	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO.	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB?	
SHOW BY DIAGRAM RELATION OF LATERAL TO WAL	NAME OF CONTRACTOR  L OF BUILDING SERVED.  D ATTERAL UNLESS THEY DIG
and the second of the second o	the control of the co

SIGNED			FILED	ΑT	ENGINEER'S	OFFICE
		Inspector for City		•••		
	•				-	

**№** 8627

## OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

	MASSILLON, OHIO, MASSILLON, OHIO,	13
RECEIVED OF Beaun 6 Lean		
FOR WHICH PERMISSION IS GRANTED Firet Ja	vend & Loan Co.	,
CUT O = F Sanitary SE		
of 6 W E . ST. TY		
THE PREMISES BEING LOT NO. 265	•	
VORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO		
OF THE DEPARTMENT OF PUBLIC SERVICE.		
NAME OF CONTRACTOR Deauce		

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.