Nº 8630 FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED $4-1-73$	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	
HOUSE NO. 1211		
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	
WAS LATERAL AT COMP.		
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR DI MALAVITE	
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.		
· · · · · · · · · · · · · · · · · · ·	1 00.	
1/	The state of the s	
SIGNEDInspector for City	FILED AT ENGINEER'S OFFICE	
f_0Y		
REMARKS	-ASURMENTS DID NOT CALL INSP	

Nº 8630

OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

1	MASSILLON, OHIO,	
RECEIVED OF Paul Newva	Shy FEE OF \$ 2	
FOR WHICH PERMISSION IS GRANTED Paul 1		
TO TAP Sassitary SEWE		
OF Stranghill and 71. E. St. TYPE		
THE PREMISES BEING LOT NO. 12857	\mathscr{J}	
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND OF THE DEPARTMENT OF PUBLIC SERVICE.		
NAME OF CONTRACTOR DILAMATE		

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.