## $N^{\circ}$ Following data to be answered by inspector and signed when returned

DATE INSPECTED 3-27-73	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO. 569	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH  219  SOUTH o SMH & C
WAS LATERAL AT CURB?	
WAS ATTACHED TO MAIN NO SHOW BY DIAGRAM RELATION OF LATERAL TO WALL	NAME OF CONTRACTOR CY 257 EXCA.  L OF BUILDING SERVED.
	4/00/1
	75"
SIGNED Thispector for City	FILED AT ENGINEER'S OFFICE.
mispector for City	

## Nº 8631

## OFFICE OF THE DIRECTOR OF PUBLIC SEF PERMIT TO TAP SEWER

MASSILLON, OHIO, 21/aux 13
RECEIVED OF CUIT FRANKLING Law. FEE OF \$ 25
FOR WHICH PERMISSION IS GRANTED HAW THE
to tap January Sewer on the 2/65
OF 15 th St. DIN. AVE. TYPE OF STREET Child & Low
THE PREMISES BEING LOT NO. 7084-7085 , HOUSE NO. 569
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND OF THE DEPARTMENT OF PUBLIC SERVICE.
NAME OF CONTRACTOR LOCAL

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.