## J FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 5-31-73	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM		
HOUSE NO. 2032 SIZE OF PIPE USED 64	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	· ····	<u></u>
WAS LATERAL AT CURB?		•	
WAS ATTACHED TO MAIN YES	NAME OF CONTRACTOR	BEAUER	EXCAL
SHOW BY DIAGRAM RELATION OF LATERAL TO WAL	L OF BUILDING SERVED.		20'
			34 141
SIGNED Jatton	FILED AT ENGI	NEER'S OFFICE	x6 -170p
Inspector for City			
REMARKS	• •		

Nº 8637

## OFFICE OF THE DIRECTOR OF PUBLIC SEF PERMIT TO TAP SEWER

	MASSILLON, OHIO, March	28 ,
\	Plaza FE	
	, 0	
FOR WHICH PERMISSION IS GRANTED	·	
TO TAP Santani SEWI	er on the Acti	
OF Lincoln Uky & AVE. TYPI	E OF STREET	·
THE PREMISES BEING LOT NO. 0.1330	ноиѕе NO. 2032-	Thea
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. OF THE DEPARTMENT OF PUBLIC SERVICE.	19-1971 DULY PASSED BY THE CITY CO	DUNCIL, AND

Note: This permit covers work outside of building boly

Note: This permit covers work outside of building buly. Any work walls of building is subject to Massillon Board of Health Regulations.