

18-2

✓
FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

Nº 8639

DATE INSPECTED

6-12-73

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO.

306

SIZE OF PIPE USED

6 1/2

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
~~CURE~~ LINE AND DEPTH

19' east of M 10' c

WAS LATERAL AT CURE?

Prop

yes

Prop


WAS ATTACHED TO MAIN

No

NAME OF CONTRACTOR

F. STEINBACH

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

J. Latham

Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

Spec.
No. 8639 ✓

OFFICE OF THE DIRECTOR OF PUBLIC SEWERS
PERMIT TO TAP SEWER

MASSILLON, OHIO, *April 2*

RECEIVED OF *Jesse Beil*

FEE OF \$ *2*

FOR WHICH PERMISSION IS GRANTED

TO TAP *Sanitary*

SEWER ON THE *North*

OF *Lorie*

AVE.
ST. TYPE OF STREET *Chippewa*

THE PREMISES BEING LOT NO. *12546*

HOUSE NO. *306*

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR *Steinbach*

**Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.**