

1-23

N^o 8641

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 5-3-73

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO. 518

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

SIZE OF PIPE USED 4"

WAS LATERAL AT CURB?


WAS ATTACHED TO MAIN

NAME OF CONTRACTOR

BEAVER EXCA.

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

TRIMONT



SIGNED J. Lathan
Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

Cost - 48
Nº 8641

OFFICE OF THE DIRECTOR OF PUBLIC SEI
PERMIT TO TAP SEWER

MASSILLON, OHIO, *April 4*

RECEIVED OF *Bureau Engineering*

FEE OF \$ *5*

FOR WHICH PERMISSION IS GRANTED *Standard Oil Co.*

Cost - 48
TO-TAP *Sanitary*

SEWER ON THE *North*

OF *Turner Ave. S.W.*

AVE.

ST. TYPE OF STREET *Hard by same*

THE PREMISES BEING LOT NO. *1832*

HOUSE NO. *518*

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR *Bureau*

**Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.**