FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 5-9-73	IF SO HOW AND LOCATION FROM STUB. IN MY 10'0-
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB?	NAME OF CONTRACTOR NO LOPY 13 AUN
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR
SHOW BY DIAGRAM RELATION OF LATERAL TO WAL	L OF BUILDING SERVED.
	31 55000
	22BenD 120
J ₂	22 Beno
	18'0 10'0EEP
SIGNED 1 Common Signed	FILED AT ENGINEER'S OFFICE
Inspector for City	
the state of the s	·

№ 8647

OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

	MASSILLON, OHIO, CLORE 30
RECEIVED OF Africal Colored	MASSILLON, OHIO, Clark 30 FEE OF \$ 25
for which permission is granted Macs 12	he 7.71
то тар <i>Далибо</i>	VER ON THE 2/22/
of Call (f)/)/ AVE. TY	
THE PREMISES BEING LOT NO. 6 4	, HOUSE NO. 814
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO OF THE DEPARTMENT OF PUBLIC SERVICE. NAME OF CONTRACTOR ACCORDANCE WITH ORDINANCE NO OF THE DEPARTMENT OF PUBLIC SERVICE.	D. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.