## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

	DATE INSPECTED 6-19-73	IF SO HOW AND LOCATION FROM 311 East of M 5 DE45
	HOUSE NO. 1621	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
	WAS LATERAL AT CURB?	
	WAS ATTACHED TO MAIN	NAME OF CONTRACTOR HOLD EREAHM
	SHOW BY DIAGRAM RELATION OF LATERAL TO WAL	L OF BUILDING SERVED. Lateral Back of house
	· · · · · · · · · · · · · · · · · · ·	4 Ji Back of Korese
		300331 2 6'A
•		5'D 93' 44'3
		21/ 85' -
	a. D. 01	450 BEND
	SIGNED William Hamme Inspector for City	FILED AT ENGINEER'S OFFICE

## Nº 8654

## OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

	MASSILLO					4, оню, <u>12/24/16</u>				
RECEIVED OF	18.5.6	1 : : 1 / 1 o	( <u></u>					FEE OF \$	رگة آبور (1.	
FOR WHICH PERMISSION					1					
TO TAP			SEWEF	R ON THE		/				
or_/ <i>La_i_</i> /	<u> </u>	<u>. Maki</u>	AVE. ST. TYPE	OF STREET	· 	Alte.	<u> </u>			
THE PREMISES BEING LO	DT NO,∠,∠	2 <u>1.34</u>	4727	<u>.37</u> ×	/ , HOU	SE NO	16.11			
WORK TO BE DONE IN A	CCORDANCE	WITH ORDII								
NAME OF CONTRACTOR	1/2/	- 12 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	مسيئة وست	~~						

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.