

N^o 8662

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

DATE INSPECTED 8-22-73

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

Wye 19' EAST OF MAIN

HOUSE NO.

1330

SIZE OF PIPE USED

4"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

WAS LATERAL AT CURB?

NO

EXIST LAT.


WAS ATTACHED TO MAIN

YES


NAME OF CONTRACTOR

G. HOLDERBAUM

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



LAT. TO THIS BUILDING



SIGNED

V. Latham

Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

N^o 8662OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWERMASSILLON, OHIO, June 27RECEIVED OF HalderhausenFEE OF \$ 25FOR WHICH PERMISSION IS GRANTED Campbell Oil Co.TO TAP SanitarySEWER ON THE EastOF Eric St. S.

AVE.

ST. TYPE OF STREET Hard surfaceTHE PREMISES BEING LOT NO. 9998HOUSE NO. 1330WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.NAME OF CONTRACTOR Halderhausen

Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.